



WHY WORK HARDER?

**WORK  
SMARTER**

## GA TO GAQ CONVERSION GUIDE

Colour	M size	GAQ Prod No.	Length, mm	Corresponding GA Prod No.	Length, mm
●	M3	GAQ M3x15	15	GA 0100×050 GA 0109×050	12,7 12,7
		GAQ M3x25	25	GA 0109×075 GA 0100×100	19,1 25,4
●	M4	GAQ M4x12 H	12	GA 0148×050	12,7
		GAQ M4x20	20	GA 0148×0750	19,1
		GAQ M4x30	30	GA 0148×100	25,4
●	M5	GAQ M5x15 H	15	GA 0187×050	12,7
		GAQ M5x25	25	GA 0180×100	25,4
		GAQ M5x35	35	GA 0187×100	25,4
●	M6	GAQ M6x11 H	11	GA 0234×0500	12,7
		GAQ M6x18 H	18	GA 0223×075 GA 0223×100	19,1 25,4
		GAQ M6x30	30	GA 0234×100 GA 0223×150	25,4 38,0
		GAQ M6x42	42	GA 0234x150	38,0
●	M8	GAQ M8x8 H	8	GA 0295×050	12,7
		GAQ M8x15 H	15	GA 0295x100	25,4
		GAQ M8x22 H	22	GA 0312x100	25,4
		GAQ M8x35	35	GA 0295x150	38,0
		GAQ M8x42	42	GA 0312×150	38,0
		GAQ M8x56	56		
●	M10	GAQ M10x10 H	10		
		GAQ M10x18 H	18		
		GAQ M10x25 H	25	GA 0375x100	25,4
		GAQ M10x40	40	GA 0375x150	38,0
		GAQ M10x70	70		
●	M12	GAQ M12x25 H	25	GA 0468×100	19,1
		GAQ M12x40	40	GA 0456×150	38,0
		GAQ M12x80	80		
●	M14	GAQ M14x40	40	GA 0535×150	38,0
		GAQ M14x80	80	GA 0535×300	76,2
●	M16	GAQ M16x40	40	GA 0600×150	38,0
		GAQ M16x80	80	GA 0625×150 GA 0625×250	38,0 63,5